



*Providing Parts to the
Aerial Lift Professional*



Product Enhancement Bulletin

Symptom : Jerky Functions with the 113070-000

If your having trouble with the 113070-000
Replace with the 065512-000



065512-000



113070-000